



# GTEN 2019 Symposium

October 21-23, 2019 | Banff, Alberta

## Gas Turbine Repair Metallurgy

Scott Hastie P. Eng & Kevin Wiens P. Eng  
Liburdi Turbine Services

Presented at the Gas Turbines Energy Network (GTEN) 2019 Symposium  
Banff, Alberta, Canada - October 2019

The GTEN Committee shall not be responsible for statements or opinions advanced in technical papers or in symposium or meeting discussions.



# Agenda

- Additional Reading
- Why repair gas turbine components?
- Materials
- Metallurgical Analysis Case Studies



## Additional Resources

- [www.gten.ca](http://www.gten.ca)

### RESOURCES FROM EVENTS:

#### 2018 GTEN WORKSHOP

##### Presentations

- GT Basics and Unit Types, Applications
- HRSGs, Combined Cycles and Cogeneration
- Flexibility with Renewable Energy
- Natural Gas Pipeline Compression
- Capital and O&M Costs
- GT Combustion and Emissions
- Standards for GHG and Air Pollution Emissions
- Panel Discussion: Clean Energy Synergies and Tradeoffs - Rainer Kurz
- Panel Discussion: Clean Energy Synergies and Tradeoffs - Manfred Klein
- Panel Discussion: Clean Energy Synergies and Tradeoffs - Amanda McAlorum

[Go to Top of Page](#)

#### 2017 IAGT SYMPOSIUM

##### Papers

- 17-IAGT-101 - SGT-750 Fuel Flexibility, Engine and Rig Tests
- 17-IAGT-102 - (Presentation Only)
- 17-IAGT-103 - Titan 250 Gas Turbine Development
- 17-IAGT-104 - Siemens Introduces the SGT-A45 Mobile Unit: Superior Performance with Trusted Technology



## Additional Resources

18<sup>TH</sup> SYMPOSIUM OF THE INDUSTRIAL APPLICATION OF GAS TURBINES COMMITTEE  
BANFF, ALBERTA, CANADA  
OCTOBER 19-21, 2009



2009-IAGT-303

### THE ROLE OF METALLURGICAL ANALYSIS IN GAS TURBINE MAINTENANCE

P. Lowden<sup>†</sup>, S. Turcott, M. Perrin, S. Hastie

*Liburdi Turbine Services ([†plowden@liburdi.com](mailto:plowden@liburdi.com))*

**Keywords:** *Metallurgical Life Analysis, Reparability, Maintenance*

#### Abstract

Metallurgical analysis of gas turbine blades to characterize component degradation can be used to assess the reparability of the blades, identify abnormal or detrimental engine operating conditions and define the potential for service interval extension. The following paper summarizes the role of metallurgical analysis in managing the operation and maintenance of turbine blades to reduce costs and improve reliability. The implications of various types of damage on operation and maintenance, including material degradation, coating degradation, hot corrosion, impact damage and damage within the internal passages will be discussed.




# Why repair gas turbine components?


- Maintenance after fuel is the main operating cost over the life cycle of a GT
- Spare part replacement and repairs of hot section components represent the major cost portion of all maintenance
- Typically component repairs cost 10% to 30% of the replacement new part cost
- Repairs represent main cost savings opportunity to the engine operator




## What gets repaired?




Acceleration  
Expansion



Deceleration  
Contraction



Thermal Mechanical  
Fatigue Cracks







## What are the materials?

### Compressor

Some 300SS  
403, 410, 422,  
450 Stainless  
IN718  
Ti64 titanium

### Combustor

300SS  
Hastelloy-X, RA-33  
IN-600, IN-617  
Nimonic 75, Nimonic 263  
Haynes 230

### Compressor Casings

Grey Cast Iron  
Carbon Steel  
Aluminum

### Turbine Shells

Ductile Cast Iron  
Stainless Steel  
Nickel Alloy

### Compressor Wheels/Disks

Ni-Cr-MO-V  
Forging

### Turbine Wheels/Discs


Ni-Cr-MO-V Steel  
Cr-Mo-V Forging  
12Cr Stainless  
Disalloy  
A286  
IN718

### Turbine Rotating




N105, N108, N115, Waspalloy, U-500, U520,  
U700, U710, U720, INX750, IN738,  
Rene80, GTD111, Mar-M247, Mar-M002,  
PWA1483, CMSX4, ReneN5

### Turbine Stationary

300SS, 400SS, C242, C1023  
N-155, M509, HS-188, L605  
X-40, X-45, FSX-414, ECY-768  
IN738, R80, GTD222, GTD444



## What are the Materials?









# Gas Turbine Blades

- Operate in high temperature and high stress service
- Each blade extracts as much power as a race car engine



## Superalloys

- $\gamma'$  structure provides nickel alloys strength at high temperature
- This structure degrades over time reducing strength of material





# Metallurgical Analysis

- Predominantly a destructive analysis of one or more turbine blades to identify issues not detectable using traditional non destructive testing (NDT)
- Evaluate microstructure
- Evaluate internal surfaces and features
- Investigation of indications found by NDT




# Metallurgical Analysis Case Studies

- A selection of recent metallurgical findings on various gas turbine components
- Investigation of indications discovered with traditional NDT
- Discovery of conditions that typical NDT would not detect



## SGT100 HPT Blades


- Creep voiding in the shroud/ airfoil radius






# SGT100 HPT Blades

- No overaging of the microstructure – voiding due to excessive stress
- Modification of the shroud required to reduce cantilevered load (stress)



Root





Airfoil





## SGT-A35 24G HPT Blades


- Extent of over-aging after 24k hours greater than mean aging from prior analyses of component, suggesting higher than nominal temperature.
- Rejuvenation applied earlier than typical (48k hours)



Mean aging after 24k hours





Root





## GE LM2500 HPT1 Blades

- 'marinized' coating (CoCrAlY outer layer; CoNiCrAlY inner layer) identified.
- Cracking mostly confined to outer CoCrAlY outer layer, but also penetrated into the base material.








# GE LM2500 HPT1 Blades

- CoCrAlY's have optimal hot corrosion resistance but prone to cracking (brittle).
- Pt-Al coating substituted for crack resistance and acceptable hot corrosion resistance





## GG8 Stage 2 turbine blades

- Significant Type-I (high temp) hot corrosion damage of seal fins identified. PWA1484 (single crystal) base alloy prone to hot corrosion attack (low Cr).
- MCrAlY coating applied to airfoil but not outer shroud surfaces
- Solution: Higher Cr weld filler; MCrAlY shroud



## GT8B Stage 1 Blades


- Tip material loss due to oxidation. Previous repair weld filler material identified as IN625 which has relatively low oxidation resistance.
- Upgrade to oxidation resistant weld filler to better maintain tip clearance





## GE Frame 7EA Stg 1 Bucket



- Poor internal coating coverage – likely as-manufactured condition, as bare surfaces had only minor oxidation damage.
- Internal coating to be replaced, but regions of oxidized base material may have less than ideal coating so continued monitoring required






## SGT-A35 24G HPT Blades

- Intergranular oxidation (up to 0.017-inches) of internal airfoil surfaces, significantly deeper than observed in prior analyses.
- Blades retired from service



## Trent 700 IPT Blade

- Shank surfaces not coated. Type-II (low temp.) hot corrosion pitting observed. Base alloy (CMSX-4 – single crystal) prone to hot corrosion (low Cr).
- Si-Al aluminizing recommended for shank and under-platform surfaces.





# Summary

- Gas turbine blades tell us a story about their service
- Metallurgical analysis is an important tool to inspect for conditions not detectable using external inspection, investigate indications found with traditional NDT and confirm and verify repair methods



# Gas Turbine Repair Metallurgy

Any Questions?